Oil Field Environmental Incident Summary

Responsible Party: FOUNDATION ENERGY MANAGEMENT, LLC **Well Operator:** WHITING OIL AND GAS CORPORATION

Well Name: PROVIDENT LIFE 43-21

Field Name: PLAZA Well File #: 12842

Date Incident:7/26/2016Time Incident:08:00Facility ID Number:County:MOUNTRAILTwp: 152Rng: 88Sec: 21Qtr:

Location Description:

Submitted By: Caitlin O'Hair Received By:

Contact Person: Caitlin O'Hair

16000 NORTH DALLAS PARKWAY, SUITE 875

DALLAS, TX 75248

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building: 4329.7 Feet

Distance Nearest Water Well:

Type of Incident: Stuffing Box Leak

Release Contained in Dike: Yes - On Facility Site Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	2	Barrels	2	Barrels	2	barrels
Brine	2	Barrels	2	Barrels	2	barrels

Other

Description of Other Released Contaminant:

Inspected: Written Report Received: 9/12/2016 Clean Up Concluded: 8/26/2016

Risk Evaluation:

There is no immediate risk to land/water/people within the area.

Areal Extent:

Spill was contained on the well facility.

Potential Environmental Impacts:

The only impacted area would be the soil around the wellhead.

Action Taken or Planned:

The spill was cleaned up with a vac truck. We are fixing the leaking stuffing box and are looking to add stuffing box containers on wellheads as well as pressure kills on the tubing.

Wastes Disposal Location: Recovered oil and saltwater will be put back into the storage tanks

onsite.

Agencies Involved: Was called in to the NDIC on 7/26/2016 and a voicemail was left for Dave

Hvinden.

Updates

Date: 7/27/2016 Status: Reviewed - Assigned to Other Agency Author: O'Gorman, Brian

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to a stuffing box leak, remained on the facility site according to the report. NDIC retains oversight.